

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 21, 2007

Nathan Smith, Administrator Hillcrest 1093 S Hilton Boise, ID 83705

License #: RC-603

Dear Mr. Smith:

On December 6, 2006, a life safety code survey was conducted at Hillcrest. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Taylor Barkley, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

TB/slc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

December 13, 2006

Eric Bultez, Administrator Hillcrest 1093 S Hilton Boise, ID 83705

Dear Mr. Bultez:

On December 6, 2006, a life safety code survey was conducted at Hillcrest. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by January 5, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION COMPLETED IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A BUILDING B. WING 13R603 12/06/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **1093 S HILTON HILLCREST BOISE, ID 83705** (X5) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R 000 R 000 Initial Comments The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on December 06. 2006. The surveyor conducting the survey was: **Taylor Barkley** Health Facility Surveyor Fire / Life Safety Bureau of Facility Standards TITLE (X6) DATE

43GB21

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

If continuation sheet 1 of 1



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

Facility Name	Physical Address	Phone Number
Hillorest Retirement Assisted Liling	1093 S. Hilton	208-345-4460
Administrator	City	ZIP Code
Nathan Smith	Boise	83705
Survey Team Leader	Survey Type	Survey Date
TAYLOR BAYKLEY	Ą	12.6.6

	CORE ISSU			
ITEM #	RULE # 16.03.22		DATE RESOLVED	BFS USE
1	410.01	Written AGreement for Relocation. The facility does not	2-16-7	10 (5 (1 (5)) 11 (5) (1 (5))
		have A written AGreement in place.	Complete	1
		ę .	77h	
a.	410.02	Fire Drills. The facility did not conduct one drill per	/ \ <u>'</u>	5.003(85)
		shift per auarter as required.		51 (\$2.50 (\$2.50) 2-10 (\$5.00) 2-10 (\$5.00)
		1		
3	404.01	The North wing And East wing stainwells do not have		1000
		A source of heat. The sprinkler system in the stairwells		
		is A wet type system. This condition pages A scuere		60 60 60 60 40 60 60 60 60
		risk of the sprinklers to freeze, A provision shall be		10.54
v		MADE to protect sprinklers from freezing.		8.87
				10 (\$10) (\$10) 10 (\$10) (\$10)
4	405,01.6	Extension COVDS And multiple Adapters, Resident Room # 120		100000000000000000000000000000000000000
		had 2 multiple adapters and a extension cords inuse	4	
				1/2/2007/00 (0 1/2/2007/00 (0
				00000000000000000000000000000000000000
	se Required Date	Signature of Facility Representative	Date Signed	
1 - (2 - 7	Vyle J. Brochs	Value of the state	